

Updates in Novapoint Tunnel

FIXED: Scanner data points and triangulated surface was shown with wrong height in the Tunnel Design dialog and Cross Section drawings. This is now corrected.

FIXED: For some projects the Tunnel Design dialog didn't open. This is now fixed.