

Version 21.FP3b

Updates in Novapoint Tunnel

CORRECTED: The triangulation functionality is now working as it should.

CORRECTED: Several errors are corrected in the functionality for LandXML export of closed tunnel profiles.